

REVISION....ADDENDUM ONE to

## **PARKING LOT RESURFACING**

Bid# 17-10

**The following questions were received during and after the pre bid meeting. The answers provided shall become part of the scope of work and conditions of the bid.**

1. ***Clarify the number of coats of product.*** Apply primer to areas that are so damaged that the material supplier has determined the product will not perform unless primed. Apply one (first) Coat of sealer to drive lanes only using a squeegee, then apply 2 more coats to entire parking lot using spray application. Recommended application rates are 0.12 to 0.15 gal/s.y. for first coat; 0.10 to 0.12 gal/s.y. for second coat; and 0.08 to 0.11 gal/s.y. for third coat.
2. ***Is power washing allowed for cleaning?*** Clean surface only by flushing.
3. ***What product was used when lot was restored in 2011?*** The product used was PMM (Polymer Modified Masterseal) by SealMaster.
4. ***Clarify the quantity of cracks requiring repair.*** It is the bidder's responsibility to determine the quantity of cracks requiring repair by visiting the site and examining the drawing notes and specifications.

END OF ADDENDUM ONE